A completed **Annual Review form and Cover Letter/Field Report** must be submitted to the Chief Engineer within **30 days** from completion of the inspection.

	Inspection Report					
Inspection ID/Docke	et	7817				
Inspector	Inspector David Cullom 11/15/2019					
Name &						
Submit Date	Submit Date					
Chief Eng		Joe Subsits 11/19/2019				
Name &						
Review/Date						
		Operator Information				
Name of Operator:	North	west Natural OP ID #:	13840			
Records Location:	Portla	nd, Oregon				
Inspection Date:	3/13/2	2019 and 11/6/2019				

Review Summary:

This annual review contains information derived from operator interviews, annual reports, DIMP/TIMP updates, Pipeline Replacement Plans, and specialized program reviews.

HQ Address:	System/Unit Name & Ad	ldress:			
220 Northwest 2nd Avenue	Headquarters				
Portland, Oregon 97209	220 Northwest 2nd Avenu	ie			
	Portland, Oregon 97209				
Co. Official: Jon G. Huddleston	Phone				
Phone No.: (503) 721-2522	No.: Fax	No.: Fax			
Fax No.: (503) 220-2584	No.:	No.:			
Emergency Phone No:(503) 226-421	1 x4613 Emergency Phone No.:	Emergency Phone No.:			
Persons Interviewed	Title	Phone			
Jaimie Lemke	Code Compliance Specialist	(503) 226-4211 x4316			
Margaret Locke	Compliance Engineer	ce Engineer (503) 226-4211 x4306			
Samantha Rookstool	Code Compliance Specialist	(503) 226-4211 x4366			
Ryan Truair	Interim Sr. Manager of Compliance	(503) 226-4211 x4361			

Syste	System Operations					
Number of reportable safety related conditions last year: 0 per Part F and G of the Annual Report.	Number of deferred leaks in system: 1					
Number of <u>non-reportable</u> safety related conditions last year 0 per Part F and G of the Annual Report	Number of excavation damage hits last year: 97 total 7 "Other"					
Miles of transmission pipeline within company (total miles and miles in Class 3 & 4 locations):	Miles of main within company (total miles and miles in Class 3 & 4 locations):					
8" Transmission is 3.5 per 2018 AR and is in a Class 3 location. This includes .1 mile that is under 20% SMYS	1899.8 miles of main (2018) not spilt out by Class locations 1841.6 miles of main (2017) not spilt out by Class locations					
Operating Pressure(s) in psig:	System MAOP(s) in psig:					
8" Transmission 330 psig (2017) DN	8" Transmission 400 psig (2017) DN					
Did not visit this site (2017) DN	Felida Gate 809 psig (2017) DN					
Did not visit this site (2015) DR	N Vancouver Gate (Williams provides pressure regulation) Inlet 960 outlet 255					
610 Inlet/218 outlet (2015) DR	5207 NW McCann Inlet 809 outlet 250 (2015) DR					
607 Inlet/510 outlet; 607 Inlet /490 outlet; 510 inlet /227 outlet (2015) DR	W. Vancouver Gate Inlet 809 outlet 250 (2015) DR					
Did not visit this site (2015) DR	Camas Gate Inlet 400 outlet 60 (2015) DR					
Did not visit this site (2015) DR	Washougal Gate Inlet 250 outlet 40 (2015) DR					
Did not visit this site (2015) DR	NE Union Rd @179th St Inlet 960 outlet 250 (2015) DR					
Did not visit this site (2015) DR	Battleground Gate Inlet 250 outlet 60 (2015) DR					
Did not visit this site (2015) DR	Ridgefield Gate Inlet 809 outlet 250 (2015) DR					
Did not visit this site (2015) DR	NW Pacific Hwy & 995 E. Wellman Rd Inlet 960 outlet 60 (2015) DR					
North Bonneville 97 (2014) DC	North Bonneville 150 (2014) DC					
Carson 142 (2014) DC	Carson 150 (2014) DC3					
White Salmon (White Salmon and Bingen run together.)148 (2014) DC	White Salmon (White Salmon and Bingen run together.) 160 (2014) DC					
Klickitat 80 (2014) DC	Klickitat 500 (2014) DC					
Dallesport 160 (2014) DC	Dallesport 250 (2014) DC					
John Day On Nitrogen – idle (2014) DC	John Day On Nitrogen – idle (2014) DC					
Does the operator have any transmission pipelines?	Yes					
Compressor stations? Use Attachment 1.	No					

Pipe Specifications:						
Year Installed (Range)	Distribution 1950-present	Pipe Diameters (Range)	Distribution ¹ /2"-12"			
	Transmission 1950- 1959 8"		Transmission 8"			
Material Type	PE and Steel	Line Pipe Specification Used	API5L and ASTM D2513			

Mileage	8" Transmission is 3.5 miles per the 2018 AR 3.4 miles reported in 2017. Part (PT and ILI info) has 3.6 miles listed. There is a difference of .1 mile in the 2018 report.	SMYS %	8" Transmission is Greater than or equal to 20% SMYS but less than 30% SMYS.
---------	--	--------	--

	REVIEW QUESTIONS	S/Yes	U/No	N/A
1.	Was the Annual Report reviewed for accuracy and trends? If any trends discovered, please	Х		
	describe:			
	Items noted were:			
	Annual Report Excavation Damage Cause:			
	Locating practices not Sufficient: There were 15 reported by NWN on the 2017 Annual Report. It went down to 2 in 2018. This appears to be a favorable trend, but many factors can influence this outcome.			
2.	For transmission operators, has the operator submitted information to the NPMS database, along with changes made after the original submission?	Х		
	Additionally, to meet the UTC requirements under RCW 81.88.080 The operator has this procedure in their manual:			
	"In January of each year, provide accurate maps of pipelines that are operating over two hundred fifty pounds per square inch gauge to the WUTC. The WUTC needs to receive notification even if changes to the required pipeline facilities do not occur."			
	Checking with Commission GIS staff earlier in 2019, NWN has provided sufficient updates to our GIS as required for this cycle.			
3.	Were there federally reportable incidents during the previous year? 0	Х		

4. Were Incident reports reviewed for accuracy and trends? If any trends discovered please describe:	X		
NWN has 15 2019 incident notifications. No Federal reportable incidents for the operator in 2019.			
1e - unscheduled interruption of 25 or more 2a - blowing gas > 2 hours 2b - high pressure, transmission			
1e - unscheduled interruption of 25 or more			
1c - evacuation of building or HCA structure or area			
1c - evacuation of building or HCA structure or area 1c - evacuation of building or HCA structure or area			
2a - blowing gas > 2 hours			
2a - blowing gas > 2 hours			
1c - evacuation of building or HCA structure or area			
1c - evacuation of building or HCA structure or area			
2a - blowing gas > 2 hours			
2a - blowing gas > 2 hours			
1c - evacuation of building or HCA structure or area 2a - blowing gas > 2 hours			
1c - evacuation of building or HCA structure or area 1c - evacuation of building or HCA structure or area			
1c - evacuation of building or HCA structure or area			
re - evacuation of bullding of men structure of area			
The incidents are primarily caused by 3 rd party damages. There were no apparent trends associated with, for example, operator error, corrosion, or material failure.			
5. Were there reportable or unreportable safety related conditions during the previous year? If			Х
yes please describe. Please refer to Column 1 Row 2 in the header. This is a repeated question.			
6. Were there any abnormal operating conditions (as described in 49 CFR 192.605 (c) or 49			Х
CFR 195.402(d))? If yes please describe. None per clarifying discussion on 11/6/2019			
7 Were there changes to the O&M Manual during the previous year?	Х		
The Field Operations Manual changes are very detailed with page and procedure numbers.			
Release March 23, 2018 changes are found in the following subject matter areas:			
Responding to Venting Reliefs			
Installing District Regulators and Reliefs			
Activating District Regulators and Reliefs			
Maintaining District Regulators and Reliefs			
Maintaining Worker Monitor and Monitor Worker Regulators			
Installing Primary Service Regulators			
Activating Primary Service Regulators			
Maintaining Primary Service Regulators Deactivating Meters			
Glossary			
Setting Pressure			
Hard Copy Forms			
The Field Operations Manual is now available online at fom.nwnatural.com	1	1	

	nges acceptable? Yo	es			Х	
			changes are communicated throu		Х	
hanges.			P, DIMP, and O&M plan and pro			
organizati controls] applicable standard o Additional each cover parties by	on (i.e., PRISM, St .). Change for the and current Stand operating procedur lly, for internal co red pipeline segmen	andard Pra purpose of lard Practi res, or equi mmunication and to th tranet upda	ange processes to manage change actice, Project Systems [SAP Proj MOC is generally defined as a de ces, Engineering or Material Spec valent." TIMP Rev 19 3/29/2019 on, "NW Natural communicates c he integrity management plan to a ates, meetings, refresher training	ect viation from cifications, changes to ffected		
	gency plans changed		previous year?			X
Below is th major cha		from NWN	N's EP. It was reviewed but there	were no		
Date	Section/Pages	Rev	Primary Change	Approved		
August 2017	Full Plan	2016- 00	Comprehensive update of plan, including reorganization of	T. Felix		
August 2018	Full Plan	2018- 01	Comprehensive review of Base Plan, Annexes and Tabs.	T. Felix		
]	
Were the ch hanges. Were there	nge Log – This is c	grity manag	eerformed a plan review - there we ement program (TIMP and DIMP fo Appendix M – outside of the sub <u>P Changes</u>	or LDC's)?	X	X
Were the ch hanges. Were there TIMP Chan TIMP plan	changes to the Integ nge Log – This is co	grity manag ontained in <u>TIM</u>	erformed a plan review - there we ement program (TIMP and DIMP fo Appendix M – outside of the sub <u>P Changes</u>	or LDC's)?	X	X
Were the ch hanges. Were there `IMP Cha i	changes to the Integ	grity manag	eerformed a plan review - there we ement program (TIMP and DIMP fo Appendix M – outside of the sub	or LDC's)?	X	x
Were the ch hanges. Were there TIMP Chan TIMP plan. Date 4-2-	changes to the Integ nge Log – This is co Section	grity manage ontained in <u>TIM</u> Rev	eerformed a plan review - there we ement program (TIMP and DIMP for Appendix M – outside of the subt P Changes Changed plan review dates and footers to reflect 2019 annual review. To include	or LDC's)? mitted Approved	X	x
Were the ch hanges. Were there TIMP Chan TIMP plan. Date 4-2-	changes to the Integ nge Log – This is co Section All Sections	grity manage ontained in <u>TIM</u> Rev	erformed a plan review - there we ement program (TIMP and DIMP for Appendix M – outside of the subb P Changes Changed plan review dates and footers to reflect 2019 annual review. To include page numbering. Changed cover date to reflect	or LDC's)? mitted Approved CAW	X	X

UTC Pipeline Safety Annual Review Checklist

	4/4/20	018 Charts	n back	9	add	led 2017 o	lata	CAW		
	4/4/20	018 Bottom	of pages	9	update	d REV ar	nd Date	CAW		
13	 not integrity intalgement program up to under what are the results of the operators program review (effectiveness evaluation) (DIMP every 5 years)? NWN documents the effectiveness review in Appendix E of the DIMP with charts and or data and performs this each year. Damages per 1000 locates is down from 3.7% in 2017 to 3.3% in 2018. Hazardous leaks repaired by material is only down by 1 from 2017 to 2018 for polyethylene pipe. 								X	
15	model a	s trends dev	elop.							
15	of IMP	activities) De as its assessm	nnis Ritter p ent method f	erformed a T	'IMP in CAs as	spection	year? (monito in 2018. NV d in the table HCA	VN uses	X	
	1	Lacama	Location Lacamas Heights Elem. Sch.		sites ool	0.9		dated 2016-		
	2	Lacamas	Lake Area	Identified	Sites	0.6	YES - Val 09-27	idated 2016-		
	There v	vere no repoi	table repairs	s since the las	t assess	ment dat	te.			
	НСА	Tool(s), or assessment method(s)		ent review esults	Asse	Prior essment date	Assessment date	Next Assessment date		
	1	ECDA	No Repor	table Repairs		1/2011	9/10/2016	2023		
	2	ECDA	No Repor	table Repairs	6/1	1/2011	9/10/2016	2023		
16			•	or the upcomi	ng year	? No w	ork is occurri	ng on the		 Х
	Camas P-04 line for 2019 Has appropriate DIMP remediation work occurred during the past year? (monitor progress of DIMP activities) NWN's DIMP program and NWN's Pipeline Replacement Plan (PRP) are closely related. The PRP and DIMP both indicate that the need for system replacement due to cast iron line pipe, bare steel line pipe, Aldyl-A/Aldyl-HD, corrosion, etc. does not presently exist. Celcon caps are being replaced as they are found but NWN considers the caps a lower threat. As such, DIMP pipeline system remediation work based on material type is not occurring.					Plan (PRP) em D, ey are ystem		Х		
	DIMP re AS NWN "The sir Natural :	emediation w N's PRP state ngle largest tl maintains a 1	ork occurrin s: reat to NW obust damag	g. Natural's fac ge prevention	lities is progra	s third pa um in the	There is not s arty damage. I State of Was acies, municip	NW hington to		X

	utilities, contractors, customers, the general public, and other stakeholders to reduce the number to third party damages." NWN is also working to increase the effectiveness of its Geographic Information		
	System (GIS) which is key to analyzing multiple variables for continued analysis.		
19	Were there changes to the Operator Qualification program? If yes, please describe.	Х	
	Please reference the 2019 OQ program inspection I performed in April 2019 for more detail.		
20	Is the Operator Qualification program up to date? Yes, Please reference the 2019 OQ program inspection I performed in April 2019 for more detail.	Х	
21	Are plan updates satisfactory? Please reference the 2019 OQ program inspection I performed in April 2019 for more detail.	Х	
22	Are personnel performing covered tasks (including contractors) properly qualified and requalified at intervals determined in the operators plan? Yes - Please reference the 2019 OQ program inspection I performed in April 2019 for more detail.	Х	
23	Were there changes to the public awareness program? Yes - There were section headings added in the 2019 plan. Bill messages and bill envelope messages were removed from the 2019 plan.	Х	
24	Is the public awareness program up to date? The PA program revision we currently have on file was submitted 4-15-2019. Mentioned in NWN's PA program plan is the cross reference to SP 619: "NW Natural has a written company policy, Standard Practice 619, "Customer and Public Education, "that emphasizes the importance of public awareness. This policy is available to employees through the Company Intranet. This policy is reviewed at least once every calendar year for compliance with49 CFR Part 192."	Х	
24	Are changes to the public awareness program satisfactory? I did not note any major changes to NWNs plan. The matrix on pg.40 of the plan demonstrates for each month what stakeholders were contacted and by what messaging method.	Х	
26	Is the following information on the operator's web page? (Not a regulatory question) Pipeline purpose and reliability https://www.nwnatural.com/Business/BenefitsOfGas Damage Prevention https://www.nwnatural.com/Business/Safety Pipe location information https://www.nwnatural.com/business/safety/pipelinelocationinformation How to get additional information https://www.nwnatural.com/business/safety/pipelinelocationinformation National Pipeline Mapping system https://www.nwnatural.com/business/safety/pipelinelocationinformation On call requirements (On call requirements are under earthquake preparedness) https://www.nwnatural.com/Business/Safety/EarthquakePreparedness Potential Hazards https://www.nwnatural.com/Business/Safety/SafetyTips 	X	

ention measures			
://www.nwnatural.com/Residential/Safety/EarthquakePreparedness			
/ damage recognition			
://www.nwnatural.com/Residential/Safety/GasLeaks/SmellRottenEggs			
V encroachment			
://www.nwnatural.com/business/safety/pipelinerightofway			
ine location information			
://www.nwnatural.com/business/safety/pipelinelocationinformation			
rity management programs			
://www.nwnatural.com/Business/Safety/PipelineIntegrityManagementProgram			
gency preparedness			
://www.nwnatural.com/Business/Safety/EarthquakePreparedness			
	Х		
the UIC on 4/15/19 is Revision 6.0, 12/20/2017. There were no changes.	v		
was by Lex Vinsel in 04/27/2016. NWN's annual review was performed by man on 12/07/2018 (Manager Cas Control)	Λ		
			Х
n units broken down appropriately? Do you recommend any changes to	Х		
its in terms of size? No changes in inspection unit size recommended.			
			Х
			X
operator taking appropriate actions in accordance with ADB-2014-04?			Λ
y hullotin is from two recent nincling foilures accurred on becaudour liquid			
· · · · · · · · · · · · · · · · · · ·			
oorhood in Faulkner County, Arkansas.			
ersals or conversion to service have not occurred on NWN's Camas			
	 ://www.nwnatural.com/Residential/Safety/EarthquakePreparedness :/ damage recognition :://www.nwnatural.com/Residential/Safety/GasLeaks/SmellRottenEggs W encroachment :://www.nwnatural.com/business/safety/pipelinerightofway line location information :://www.nwnatural.com/Business/Safety/PipelineIntegrityManagementProgram rgency preparedness :://www.nwnatural.com/Business/Safety/PipelineIntegrityManagementProgram rgency preparedness :://www.nwnatural.com/Business/Safety/EarthquakePreparedness :://www.nwnatural.com/Business/Safety/EarthquakePreparedness<!--</th--><th>x'/ damage recognition x://www.nwnatural.com/Residential/Safety/GasLeaks/SmellRottenEggs V encroachment x://www.nwnatural.com/business/safety/pipelinerightofway line location information x://www.nwnatural.com/business/safety/pipelinelocationinformation rity management programs x://www.nwnatural.com/Business/Safety/PipelineIntegrityManagementProgram rgency preparedness) x://www.nwnatural.com/Business/Safety/EarthquakePreparedness thauges to the Control Room Management Program? NWN's annual review was y Jeremy Coleman on 12/07/2018 (Manager, Gas Control) The version the UTC on 4/15/19 is Revision 6.0, 12/20/2017. There were no changes. the UTC on 4/15/19 is Revision 6.0, 12/20/2017. There were no changes. to room management program up to date? The Last CRM inspection performed was by Lex Vinsel in 64/27/2016. NWN's annual review was performed by eman on 12/07/2018 (Manager, Gas Control) rol room management program changes satisfactory? No changes noted since To inspection. on units broken down appropriately? Do you recommend any changes to nits in terms of size? No changes, or conversions to service since the last w reversals or conversion to service have not occurred on NWN's Camas operator taking appropriate actions in accordance with ADB-2014-04?</th><th>x'/damage recognition x'/www.nwnatural.com/Residential/Safety/GasLeaks/SmellRottenEggs W encroachment x//www.nwnatural.com/business/safety/pipelinerightofway line location information x:/www.nwnatural.com/business/safety/pipelinelocationinformation grity management programs x:/www.nwnatural.com/Business/Safety/PipelineIntegrityManagementProgram regency preparedness thquake preparedness thquake preparedness x hanges to the Control Room Management Program? NWN's annual review was x y Jeremy Coleman on 12/07/2018 (Manager, Gas Control) The version the UTC on 4/15/19 is Revision 6.0, 12/20/2017. There were no changes . I room management program up to date? The last CRM inspection performed by x was by Lex Vinsel in 04/27/2016. NWN's annual review was performed by x eman on 12/07/2018 (Manager, Gas Control) x x on units broken down appropriately? Do you recommend any changes to x x nits in terms of size? No changes in inspection unit size recommended. x x my flow reversals, product changes, or conversions to service since the last x x my flow reversals, product changes, or conversions to service on hazardous liquid are the flow had been reversed. (From the Federal Register) The Tesoro ppleline rupture was discovered on September 29, 2013,</th>	x'/ damage recognition x://www.nwnatural.com/Residential/Safety/GasLeaks/SmellRottenEggs V encroachment x://www.nwnatural.com/business/safety/pipelinerightofway line location information x://www.nwnatural.com/business/safety/pipelinelocationinformation rity management programs x://www.nwnatural.com/Business/Safety/PipelineIntegrityManagementProgram rgency preparedness) x://www.nwnatural.com/Business/Safety/EarthquakePreparedness thauges to the Control Room Management Program? NWN's annual review was y Jeremy Coleman on 12/07/2018 (Manager, Gas Control) The version the UTC on 4/15/19 is Revision 6.0, 12/20/2017. There were no changes. the UTC on 4/15/19 is Revision 6.0, 12/20/2017. There were no changes. to room management program up to date? The Last CRM inspection performed was by Lex Vinsel in 64/27/2016. NWN's annual review was performed by eman on 12/07/2018 (Manager, Gas Control) rol room management program changes satisfactory? No changes noted since To inspection. on units broken down appropriately? Do you recommend any changes to nits in terms of size? No changes, or conversions to service since the last w reversals or conversion to service have not occurred on NWN's Camas operator taking appropriate actions in accordance with ADB-2014-04?	x'/damage recognition x'/www.nwnatural.com/Residential/Safety/GasLeaks/SmellRottenEggs W encroachment x//www.nwnatural.com/business/safety/pipelinerightofway line location information x:/www.nwnatural.com/business/safety/pipelinelocationinformation grity management programs x:/www.nwnatural.com/Business/Safety/PipelineIntegrityManagementProgram regency preparedness thquake preparedness thquake preparedness x hanges to the Control Room Management Program? NWN's annual review was x y Jeremy Coleman on 12/07/2018 (Manager, Gas Control) The version the UTC on 4/15/19 is Revision 6.0, 12/20/2017. There were no changes . I room management program up to date? The last CRM inspection performed by x was by Lex Vinsel in 04/27/2016. NWN's annual review was performed by x eman on 12/07/2018 (Manager, Gas Control) x x on units broken down appropriately? Do you recommend any changes to x x nits in terms of size? No changes in inspection unit size recommended. x x my flow reversals, product changes, or conversions to service since the last x x my flow reversals, product changes, or conversions to service on hazardous liquid are the flow had been reversed. (From the Federal Register) The Tesoro ppleline rupture was discovered on September 29, 2013,

PHMSA ADVISORY BULLETINS: LINK